
	भारत सरकार / Government of India	
	केन्द्रीय लोक निर्माण विभाग / Central Public Work Department	
	कार्यपालक अभियंता गांधीनगर / Executive Engineer, Gandhinagar	
	पहली मंजिल केन्द्रीय निर्माण सदन, केलोनिवि / 1st Floor, Kendriya Nirman Sadan, CPWD	
	सेक्टर-10/A, गांधीनगर-382010 (गुजरात) / Sector-10/A, Gandhinagar (382010)	
	Tel.: (079)2322436, Fax: 23248696 (E-mail: eegcdgn.cpwd@gov.in)	
संख्या :23(30)/ काअगा/हिन्दी/2021/ 574-15		दिनांक: 13.04.2021


CERTIFICATE

The School Building of the Kendriya Vidyalaya, CRPF, Gandhinagar have been visually inspected by the undersigned & it is certified that the above said building is structurally safe and sound.

But, following observation are observed in school building are mentioned below:

1. Ceiling plaster in boys and girls toilet at ground floor has damaged at few places.
2. In new block, minor hair/shrinkage crack seen in wall plaster.
3. In one class room (opposite to boys toilet) at first floor at old balock, wall plaster found brocken at few places.
4. In examination room and in corridor at first floor iin old block, wall plaster found broken at few places.

भवदीय,


कार्यपालक अभियंता,
केलोनिवि, गांधीनगर